

STEPPING MOTORS TYPE 86BHH118-490G-5GU5K

SPECIFICATIONS				WIRING DIAGRAM	
STEP ANGLE	1.8°±5%	VOLTAGE	4.9V	红 A	
NO. of PHASE	4	CURRENT/PHASE	4.9 A	黄 B	
Inultion Resistant	100Mohm(500VDC)	INDUCTANCE/PHASE	6.5±20%mh	蓝 C	
Ambient Temperature	-20~40 °C	RESISTANCE/PHASE	1.0±10% Ω	黑 D	
Operate_Temperature	110 °C Max	HOLDING_TORQUE	62kg.cm		
WEIGHT	xxx Max				
Ratio	5:1				
The Box allowable load	20N.m MAX				

FIGURE UNIT:mm

